

INTERNATIONAL TRUCK AND ENGINE CORPORATION

4205 WINFIELD ROAD, WARRENVILLE, IL 80566

TRUCK GROUP

INTERIM NOTICE FOR SAFETY RECALL 03502

October 2003

Dear International Truck Customer:

International Truck and Engine Corporation has notified the National Highway Traffic Safety Administration of a safety defect that may involve certain bus models built from 4/1/1997 through 12/31/2002 with the Bosch DiamondLife™ Zero Offset Pin Slide hydraulic disc brake system. The brake system may experience calipers sticking in the applied position. When undetected, this condition may result in premature brake component wear, excessive or abnormal heat generation at one or more of the wheel ends, or a wheel end fire.

Once the final population and remedy have been determined, you will be notified of the actions you should take to ensure your vehicle is repaired.

If it is determined that you are NOT involved in this recall, you will NOT receive any further notification.

We appreciate your patience and cooperation regarding this campaign and apologize for any Inconvenience this may cause.

INTERNATIONAL TRUCK AND ENGINE CORPORATION